# **APPENDIX 3: Photographs of test setup**

### **Conducted Emission**



Photo 1



Photo 2

Test report No. : 4787971961-E1V2
Page : 42 of 45
Issued date : July 5, 2017
FCC ID : RYYEYSGCC

# **Radiated Spurious Emission**




Photo 1




Photo 2

# **Radiated Spurious Emission**




Photo 3





Photo 4

: 4787971961-E1V2 : 44 of 45


: July 5, 2017 : RYYEYSGCC

# Worst Case Position (Horizontal: X-axis/ Vertical:X-axis)


### X-axis



Y-axis



**Z**-axis



Test report No. : 4787971961-E1V2
Page : 45 of 45
Issued date : July 5, 2017
FCC ID : RYYEYSGCC

# **Antenna Port Conducted**




Photo 1

### **End of Report**