

COMPLIANCE
ENGINEERING
IRELAND LTD



Compliance Engineering Ireland Ltd

Clonross Lane, Derrockstown, Dunshaughlin

Co. Meath, Ireland A85 XN59

Ph +353 1 8017000 , 8256722



www.cei.ie



Contents



APPENDIX D: RADIATED SPURIOUS EMISSIONS WITH SAMPO S0 ANTENNA.....	3
APPENDIX E: RADIATED SPURIOUS EMISSIONS WITH HH8X ANTENNA.....	8
APPENDIX F: CONDUCTED EMISSIONS ON THE MAINS.....	13
APPENDIX G: BLOCK DIAGRAMS OF TEST SETUP	15

Please refer to the main document 22E9844-1a

Appendix D: Radiated Spurious Emissions with Sampo S0 Antenna










Fig D7: High Channel Radiated Emissions 3.6GHz - 10GHz, Vertical, 3metre










Fig D8: High Channel Radiated Emissions 3.6GHz - 10GHz, Horizontal, 3metre

Appendix E: Radiated Spurious Emissions with HH8X Antenna










Fig E7: High Channel Radiated Emissions 3.6GHz - 10GHz, Vertical, 3metre









Fig E8: High Channel Radiated Emissions 3.6GHz - 10GHz, Horizontal, 3metre

Appendix F: Conducted Emissions on the Mains



Appendix G: Block Diagrams of Test Setup



End of Report