

9. APPENDIX II

PHOTOGRAPHS OF TEST SETUP

Conducted Emission Setup Photo







Compliance Certification Services Inc.

Report No: 71210101-RP1

FCC ID: SETBLX1JW

Date of Issue: December 13, 2007

Radiated Emission Setup Photos





Compliance Certification Services Inc.

Report No: 71210101-RP1

FCC ID: SETBLX1JW

Date of Issue: December 13, 2007

Power Line Conducted Emissions Setup Photos

