

Comments for Upload for FCC ID: SK6XN8

Comment:

4. Internal Photographs – The internal photographs show fences for shields over the RF section of the radio boards. However, there are no photographs showing the presence of the shields. Please provide a photograph showing the shields or confirm that the RF shields are not installed in production.

Response: The shields are not required and are not installed in the production units.