

April 12, 2006

RE: Xirrus, Inc.

FCC ID: SK6XS3700A

- 1) Please update the IC Form to remove the patch antenna. Uploaded ATCB-Appendix I and II form RSP-100 (8TRx) rev 3.doc
- 2) Please updated external photographs for both applications to remove the patch antenna shown in one of the photos.

Uploaded External Photos rev2.pdf

3) Overall internal view shows all radios (16 version)....Please document with appropriate notes or correct the photograph.

Uploaded Whole Unit no top rev1.pdf

4) RF boards for the schematics are labeled dual, but appear to contain all 4 radios. Please review/correct.

Uploaded 130-0038revised.pdf

- 5) Are AC powerline test photos available. If so, please provide. Uploaded AC CE Test Configuration Photographs.pdf
- 6) Please provide the last corrected manual applicable to this device as modified for the other similar application. The manual provided appears to be the older version.

Uploaded xirrus array userguide2-1.pdf and xirrus array userguide2-2.pdf

Regards,

Mark Briggs Principal Engineer