

Report No.: EED32Q80512201 Page 32 of 42

8 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32Q80512201 Page 33 of 42



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

