

APPENDIX 3: Photographs of test setup

Radiated Spurious Emission




Photo 1




Photo 2

Worst Case Position

Below 1 GHz (Horizontal: X-axis / Vertical: X-axis)

Above 1 GHz (Horizontal: X-axis / Vertical: Y-axis)

X-axis




Y-axis



Z-axis



Antenna Terminal Conducted Tests



Photo

End of Report