

To whom ever it may concern,

I confirm that A M Bromley TMS10 tyre pressure monitor RFI report number RP46858JD01A was oriented through 3 orthogonal planes in accordance with C63.4 to determine the worse case orientation. All radiated testes were then performed in the worse case orientation.

Regards



Nigel Davison

RFI Global Services Ltd

Pavilion A, Ashwood Park, Ashwood Way, Basingstoke, Hampshire RG23 8BG

Telephone: +44 (0)1256 312000 Facsimile: +44 (0)1256 312001

Email: info@rfi-global.com Website: www.rfi-global.com

Registered in England and Wales. Company number: 2117901