


Prüfbericht - Nr.:
Test Report No.:

16009099 001

Seite 28 von 32
Page 28 of 32

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emission on AC Mains





Prüfbericht - Nr.:
Test Report No.:



16009099 001

Seite 29 von 32
Page 29 of 32

Photograph 2: Set-up for Radiation Measurement below 1GHz



Photograph 3: Set-up for Radiation Measurement above 1GHz
(1 GHz to 18 GHz)



Prüfbericht - Nr.:
Test Report No.:

16009099 001

Seite 31 von 32
Page 31 of 32

(18GHz to 26GHz)

