


Report No. : EED32N80836802



Page 50 of 52





Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)






Report No. : EED32N80836802





Page 51 of 52



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground














Report No. : EED32N80836802



PHOTOGRAPHS OF EUT Constructional Details

Refer to Report No.EED32N80836801 for EUT external and internal photos.

The test report is effective only with both signature and specialized stamp, The result(s) shown in this report refer only to the sample(s) tested. Without written approval of CTI, this report can't be reproduced except in full.

