



Test Set Up Photographs Radiated

Photograph 1: Front View Radiated Emissions, Below 1000 MHz Worst Case Configuration



Photograph 2: Back View Radiated Emissions, Below 1000 MHz Worst Case Configuration



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 3: Front View Radiated Emissions Worst Case – Above 1000 MHz Configuration



Photograph 4: Back View Radiated Emissions Worst Case – Above 1000 MHz Configuration



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 5: Vertical Configuration



Photograph 6: Flat Configuration



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 7: On Edge Configuration



Reference Test Set Up Photographs



Photograph 8: Reference Photo of Test Setup for Emissions Below 30 MHz



Photograph 9: Reference Photo of Test Setup for Emissions From 30 MHz to 1000 MHz





Photograph 10: Reference Photo of Test Setup for Emissions Above 1000 MHz