

ID: TO7D1598-S

Report No.: EF/2005/90012 **Issue Date: Oct. 03, 2005** 

## **APPENDIX 1**

## PHOTOGRPHS OF SET UP



ID: TO7D1598-S

Report No.: EF/2005/90012 **Issue Date: Oct. 03, 2005** 



## **Radiated Emission Set up Photo**





The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan. / 台北縣五股工業區五工路134號
t (886-2) 2299-3939

f (886-2) 2298-2698

www.sgs.com.tw




ID: TO7D1598-S

Report No.: EF/2005/90012 **Issue Date: Oct. 03, 2005** 

## **Conducted Emission Set up Photo**





The results shown in this test report refer only to the sample(s) tested unless otherwise stated. This test report cannot be reproduced, except in full, without prior written permission of the Company.

SGS Taiwan Ltd.
台灣檢驗科技股份有限公司

No. 134, Wu Kung Rd., Wuku Industrial Zone, Taipei Country, Taiwan. / 台北縣五股工業區五工路134號
t (886-2) 2299-3939

f (886-2) 2298-2698

www.sgs.com.tw