

Report No.: FR7D1808

Appendix B. Test Photos

FCC ID: TX2-RTL8187SE Page No. : 1 of 6



Report No.: FR7D1808

1. Photographs of Conducted Emissions Test Configuration




FRONT VIEW




REAR VIEW

FCC ID: TX2-RTL8187SE Page No. : 2 of 6





SIDE VIEW




FCC ID: TX2-RTL8187SE Page No. : 3 of 6




Report No.: FR7D1808

2. Photographs of Radiated Emissions Test Configuration

9kHz ~30MHz




FRONT VIEW



REAR VIEW

FCC ID: TX2-RTL8187SE Page No. : 4 of 6





30MHz~1GHz




FRONT VIEW



REAR VIEW

FCC ID: TX2-RTL8187SE Page No. : 5 of 6






Above 1GHz



FRONT VIEW



REAR VIEW

FCC ID: TX2-RTL8187SE Page No. : 6 of 6