




Test Set Up Photographs Radiated


Photograph 1: Front View Radiated Emissions, Worst Case – Below 1000 MHz Configuration



Photograph 2: Back View Radiated Emissions Worst Case 30 MHz to 1000 Configuration



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 3: Front View Radiated Emissions Worst Case – Above 1000 MHz Configuration



Photograph 4: Flat orientation



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 5: On Edge orientation



Photograph 6: Vertical orientation



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040




Photograph 7: Front View Conducted Emissions Worst-Case Configuration



Photograph 8: Back View Conducted Emissions Worst-Case Configuration





Photograph 9: DFS Test Setup



Reference Test Set Up Photographs




Photograph 10: Reference Photo of Test Setup for Emissions Below 30 MHz



Photograph 11: Reference Photo of Test Setup for Emissions From 30 MHz to 1000 MHz





Photograph 12: Reference Photo of Test Setup for Emissions Above 1000 MHz