


## Test Set Up Photographs Radiated



Photograph 1: Front View Radiated Emissions, Worst Case – Below 1000 MHz Configuration



Photograph 2: Back View Radiated Emissions Worst Case 30 MHz to 1000 Configuration





Photograph 3: Front View Radiated Emissions Worst Case – Above 1000 MHz Configuration




Photograph 4: Back View Radiated Emissions Worst Case – Above 1000 MHz Configuration






Photograph 5: Front View Conducted Emissions Worst-Case Configuration




Photograph 6: Back View Conducted Emissions Worst-Case Configuration



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040




Photograph 7: Flat Placement Worst Case



Photograph 8: Edge Placement



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



**Photograph 9: Vertical Placement** 



## **Reference Test Set Up Photographs**



Photograph 10: Reference Photo of Test Setup for Emissions Below 30 MHz



Photograph 11: Reference Photo of Test Setup for Emissions From 30 MHz to 1000 MHz





Photograph 12: Reference Photo of Test Setup for Emissions Above 1000 MHz