




Test Set Up Photographs Radiated

Photograph 1: Front View Radiated Emissions, Worst Case – Below 1000 MHz Configuration




Photograph 2: Back View Radiated Emissions Worst Case 30 MHz to 1000 Configuration





Photograph 3: Front View Radiated Emissions Worst Case – Above 1000 MHz Configuration



Photograph 4: Back View Radiated Emissions Worst Case – Above 1000 MHz Configuration




313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 5: Front View Conducted Emissions Worst-Case Configuration



Photograph 6: Back View Conducted Emissions Worst-Case Configuration







Photograph 7: Flat Placement Worst Case



Photograph 8: Edge Placement



313 West 12800 South, Suite 311, Draper, UT 84020 • (801) 260-4040



Photograph 9: Vertical Placement



Reference Test Set Up Photographs




Photograph 10: Reference Photo of Test Setup for Emissions Below 30 MHz



Photograph 11: Reference Photo of Test Setup for Emissions From 30 MHz to 1000 MHz





Photograph 12: Reference Photo of Test Setup for Emissions Above 1000 MHz