




INTERNAL PHOTOS

1.2 MAIN BOARD


In the enclosure



Antenna



Radio board






INTERNAL PHOTOS

Written by : O. ROY

15 May 2007

Test report # : 280104-CC-1-a



1.3 RADIO BOARD

Front side



Back side

