

Report No. : EED32P80121201

Page 32 of 42

## **9 PHOTOGRAPHS OF TEST SETUP**

Test model No.: BP3GX1-4B



Radiated spurious emission Test Setup-1(Below 1GHz)






Report No. : EED32P80121201









Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.

