






PHOTOGRAPHS OF TEST SETUP

Test Model No.: BP3KV1-5W



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)













Report No.: EED32N81431801 Page 32 of 41



Radiated spurious emission Test Setup-3(Above 1GHz) There are absorbing materials under the ground.



AC Power Line Conducted Emission









