







PHOTOGRAPHS OF TEST SETUP

Test model No.:BP3MV1-3B



Radiated spurious emission Test Setup-1(Below 30MHz)



Radiated spurious emission Test Setup-2(Below 1GHz)













Page 49 of 61 Report No.: EED32M00176801



Radiated spurious emission Test Setup-3 (Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.
























Conducted Emissions Test Setup





















































