


Report No. :EED32O81190401 Page 28 of 39

9 PHOTOGRAPHS OF TEST SETUP

Test model No.:FR1DQ1-B




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Below 1GHz) close up photo



Report No.: EED32O81190401 Page 29 of 39



Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.









