INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs

Radiated Emission

		E.
		a shirt and a shirt a shirt a shirt a
	1111,	
	RADIATED	
	Model No.: PB1000	
	Job No.: HK08 110913 -1	
	A D,B	
1 har and a second		The second second
Contraction of the second s		

Front View

1111		
RADIATED Model No.: PB1000		
Job No.: <u>HK08110913 -1</u>		
DA Ø,B		
		1
	. Yango ya	5 115 MM