Report No.: T130823L04-RP2


FCC ID: V3J-JC01


Date of Issue: October 21, 2013

8 PHOTOGRAPHS OF TEST SETUP

Radiated Emission Setup Photos

Below 1GHz









Report No.: T130823L04-RP2

FCC ID: V3J-JC01

Date of Issue: October 21, 2013

Above 1GHz








Compliance Certification Services Inc.

Report No.: T130823L04-RP2 FCC ID: V3J-JC01

Conducted Emission Setup Photo



Date of Issue: October 21, 2013



Compliance Certification Services Inc.

Date of Issue: October 21, 2013

Power Line Conducted Emissions Setup Photos



