
Report No.: EMC14141


8 TEST CONFIGURATION PHOTO

8.1 Radiated Emission Test (Axial Direction of EUT)


Pattern 1



Pattern 2



Pattern 3



Report No.: EMC14141


8 TEST CONFIGURATION PHOTO

8.2.1 Radiated Emission Test


9 kHz to 30 MHz


Pattern 1







Pattern 2





Pattern 3





This cable routing was attempted to maximize the radiated emission.


Report No.: EMC14141


8 TEST CONFIGURATION PHOTO

8.2.2 Radiated Emission Test

30 MHz to 1 GHz


Pattern 1





Pattern 2





Pattern 3





This cable routing was attempted to maximize the radiated emission.

8 TEST CONFIGURATION PHOTO

8.3 Frequency Stability Test



