
14 EXHIBIT B – Test Setup Photographs

14.1 Conducted Emissions – Front View




14.2 Conducted Emissions – Side View




Report Number: R0910282-247

Page 72 of 76



14.3 Tx and Rx Spurious Radiated Emissions (Below 1 GHz) – Front View

14.4 Tx and Rx Spurious Radiated Emissions (Below 1 GHz) – Rear View





$14.5 \quad Tx \ and \ Rx \ Spurious \ Radiated \ Emissions \ (Above \ 1 \ GHz) - Front \ View$

14.6 Tx and Rx Spurious Radiated Emissions (Above 1 GHz) – Rear View

