

Appendix C. Test Setup Photographs

Conducted Emissions Test Configuration:

Front View




Rear View



Report Number: USRC231013001



Radiated Emissions Test Configuration:




Page 2 of 4


Report Number: USRC231013001



Below 1 GHz _ Front View




Below 1 GHz _ Rear View




Report Number: USRC231013001



Above 1 GHz _ Front View



Above 1 GHz _ Rear View



Report Number: USRC231013001