



# Internal Photos of EUT

Report No.: 50264672 001

Model No. : CN28PU

Page: 1 of 6





# Internal Photos of EUT

Report No.: 50264672 001

Model No. : CN28PU

Page: 2 of 6







# Internal Photos of EUT

Report No.: 50264672 001

Model No. : CN28PU

Page: 3 of 6



# Internal Photos of EUT

Report No.: 50264672 001

Model No. : CN28PU

Page: 4 of 6







# Internal Photos of EUT

Report No.: 50264672 001

Model No. : CN28PU

Page: 5 of 6




# Internal Photos of EUT

Report No.: 50264672 001

Model No. : CN28PU

Page: 6 of 6



--THE END--