The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission - Base Unit



Front View



Rear View

The Worst Case Configuration Photographs – Mode: Transmission

Radiated Emission - Handset



Front View



Rear View

IC: 4522A-80763801 config photos (radiated emission - handset) - 2 of 2

The Worst Case Configuration Photographs – Mode: Receiving

Radiated Emission – Base Unit



Front View



Rear View

The Worst Case Configuration Photographs – Mode: Receiving

Radiated Emission - Handset



Front View



Rear View

IC: 4522A-80763801 config photos (radiated emission – handset) - 2 of 2

The Worst Case Configuration Photographs – Mode: DECT Talk with Speakerphone

Conducted Emission



Front View



Right Side View

The Worst Case Configuration Photographs – Mode: DECT Talk with Speakerphone

Conducted Emission



Left Side View

IC: 4522A-80763801 config photos (conducted emission) - 2 of 2

The Worst Case Configuration Photographs – Mode: Handset talk with charging with charger

Conducted Emission



Front View



Right Side View

The Worst Case Configuration Photographs – Mode: Handset talk with charging with charger

Conducted Emission



Left Side View