

## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Model: CB1000GNR0

Radiated Emission – Alarm Clock



Front View



Rear View

## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Model: CB1010GHR0

Radiated Emission – Alarm Clock



Front View




Rear View

## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Model: CB1000GNR0

#### Conducted Emission



Front View



Right Side View

## INTERTEK TESTING SERVICES

---

### The Worst Case Configuration Photographs – Model: CB1000GNR0

---

Conducted Emission



Left Side View

## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Model: CB1010GHR0

#### Conducted Emission



Front View




Right Side View

## INTERTEK TESTING SERVICES

### The Worst Case Configuration Photographs – Model: CB1010GHR0

#### Conducted Emission



Left Side View