



**APPENDIX 3: Photographs of test setup**

**Radiated Spurious Emission**



**Photo 1**



**Photo 2**

---

**UL Japan, Inc.**

**Ise EMC Lab.**

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN


Telephone : +81 596 24 8999

Facsimile : +81 596 24 8124


**Worst Case Position**

**Below 1GHz Horizontal: X-axis / Vertical: X-axis**  
**Above 1GHz: Horizontal: X-axis / Vertical: Z-axis**


**X-axis**




**Y-axis**



**Z-axis**



### Antenna Terminal Conducted Tests



**Photo 1**

**End of Report**