

Photo Report on Test Setups

OBDII Dongle

EP-150-A-HW A.1

Test Report Reference: MDE_JABIL_2006_FCC_Photo_Setups

Test Laboratory:

7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Deutsche
Akkreditierungsstelle
D-PL-12140-01-01
D-PL-12140-01-02
D-PL-12140-01-03

Note:

The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7layers GmbH
Borsigstraße 11
40880 Ratingen, Germany
T +49 (0) 2102 749 0
F +49 (0) 2102 749 350

Geschäftsführer/
Managing Directors:
Frank Spiller
Bernhard Retka
Alexandre Norré-Oudard

Registergericht/registered:
Düsseldorf HRB 75554
USt-Id.-Nr./VAT-No. DE203159652
Steuer-Nr./TAX-No. 147/5869/0385

*a Bureau Veritas
Group Company*

www.7layers.com




Photo 1: Test setup for radiated measurements below 30 MHz




Photo 2: Test setup for radiated measurements below 1 GHz



Photo 3: Test setup for radiated measurements above 1 GHz




Photo 4: Test setup for radiated measurements 1 GHz to 18 GHz FCC 15b



Photo 5: Test setup for radiated measurements above 26 GHz




Photo 6: Test setup for conducted measurements




Photo 7: Test setup for conducted measurements EUT Detail




Photo 8: Test setup for radiated measurements EUT Detail