


# Appendix C – SAR Test Setup Photos



# Test Position Back 0 mm Gap

## Note: Cables are removed prior to testing.



### Report Number: SAR.20220203



Test Position Left 0 mm Gap

Note: Cables are removed prior to testing.



#### Report Number: SAR.20220203



**Test Position Top 0 mm Gap** 

Note: Cables are removed prior to testing.