

Prüfbericht - Nr.:
Test Report No.:

16016884 001

Seite 28 von 30
Page 28 of 30

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emission Measurement



Photograph 2: Set-up for Radiation Measurement below 1GHz



Prüfbericht - Nr.:
Test Report No.:

16016884 001

Seite 29 von 30
Page 29 of 30

Photograph 3: Set-up for Radiation Measurement above 1GHz

