



## 6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emissions, AC Mains



Photograph 2: Set-up for Radiated Emissions, below 1GHz



**Prüfbericht - Nr.:** CN23WJ7J 001  
*Test report no.*

Seite 24 von 25  
Page 24 of 25

**Photograph 3: Set-up for Radiated Emissions, above 1GHz**

