Report No: 90813018-RP1 FCC ID:WOI-576020E34000 Date of Issue: Nov. 2, 2009

# APPENDIX II PHOTOGRAPHS OF TEST SETUP

**Conducted Emission Setup Photo** 





## **COMPLIANCE Certification Services Inc.**


Report No: 90813018-RP1 FCC ID:WOI-576020E34000

Date of Issue: Nov. 2, 2009

#### **Radiated Emission Setup Photos**

30 ~ 1000 MHz








### **Compliance Certification Services Inc.**

Report No: 90813018-RP1 FCC ID:WOI-576020E34000

Date of Issue: Nov. 2, 2009

#### **Above 1GHz**







## **COMPLIANCE Certification Services Inc.**

Report No: 90813018-RP1 FCC ID:WOI-576020E34000 Date of Issue: Nov. 2, 2009

#### **Powerline Conducted Emissions Setup Photos**



