








Page 55 of 57


Report No.: EED32O80133704

PHOTOGRAPHS OF TEST SETUP

Test model No.:D1 Pro



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Page 56 of 57 Report No.: EED32O80133704



Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.



Conducted Emissions Test Setup









