



Photos

Radio parameter test of VE312 according to FCC and IC specifications

Performed for GN Hearing A/S

Page 1 of 8

This exhibit is an extract of

DELTA Test Report T205853-3
DANAK-19/13295
14 August 2013

containing only the photos of the test set-ups

DELTA

Venlighedsvej 4
2970 Hørsholm
Denmark

Tel. +45 72 19 40 00
Fax +45 72 19 40 01
www.delta.dk
VAT No. 12275110



Photo 4.3.1 Test setup regarding measurement of radiated emission below 1 GHz.



Photo 4.3.2 Test setup regarding measurement of radiated emission below 1 GHz.



Photo 4.4.1 Test setup regarding measurement of radiated emission below 1 GHz.



Photo 4.4.2 Test setup regarding measurement of radiated emission below 1 GHz.




Photo 4.5.1 Test setup regarding measurement of radiated emission above 1 GHz .




Photo 4.5.2 Test setup regarding measurement of radiated emission above 1 GHz.




Photo 4.6.1 Test setup regarding measurement of radiated emission above 1 GHz.




Photo 4.6.2 Test setup regarding measurement of radiated emission above 1 GHz.




Photo 4.9.1 Test setup regarding measurement of 20 dB bandwidth.




Photo 4.10.1 Test setup regarding measurement of 20 dB bandwidth.




Photo 4.11.1 Test setup regarding measurement of band edge compliance.




Photo 4.12.1 Test setup regarding measurement of band edge compliance.




Photo 4.13.1 Test setup regarding measurement of occupied bandwidth.




Photo 4.14.1 Test setup regarding measurement of occupied bandwidth.