



7. Photographs of the Test Setup

Photograph 1: Set-up for Conducted RF test at Antenna Port



Photograph 2: Set-up for Radiated Emission, 30MHz-1000MHz



Photograph 3: Set-up for Radiated Spurious Emission, 1G-18GHz

Prüfbericht - Nr.: 15061569 001
Test Report No.:

Seite 41 von 41
Page 41 of 41

Photograph 4: Set-up for Radiated Spurious Emission, 1G-18GHz

