

## 1. Photograph of Liquid Depth



Photograph of the depth in the Body Phantom (835MHz, 16.2cm depth)




Photograph of the depth in the Body Phantom (1800MHz, 16.1cm depth)

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 1 of 5 SHENZHEN LCS COMPLIANCE TESTING LABORATORY LTD.

FCC ID: X7I-GK310

Report No.: LCS170928031AE4




Photograph of the depth in the Body Phantom (1900MHz, 16.0cm depth)

This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 2 of 5

## 2. Photograph of the Test Setup

### **0mm body Back Side Setup Photo**



#### 0mm body Front Side Setup Photo



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 3 of 5

FCC ID: X7I-GK310

Report No.: LCS170928031AE4

#### 0mm body-worn Left Side Setup Photo




#### 0mm body-worn Top Side Setup Photo



This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 4 of 5

# 3. EUT Photographs





This report shall not be reproduced except in full, without the written approval of Shenzhen LCS Compliance Testing Laboratory Ltd. Page 5 of 5