



1 Conducted emissions

With power supply box

Note : the final plastic clips for the charging connector was not ready for the test

This plastic clip will replace the cardboard made fixation.





EQUIPMENT FCC ID : XFJ225

Canada IC : 8392A-XP225

Exhibit 7

Test Setup Photos

Page : 2/4

Written by : O. ROY

17 December 2009

Test report # : 560101-CC-1-a

With PC power supply





2 Radiated emissions

Magnetic sensor head



Antenna in front of the equipment with turntable at 0°



EQUIPMENT FCC ID : XFJ225

Canada IC : 8392A-XP225

Exhibit 7

Test Setup Photos

Page : 4/4

Written by : O. ROY

17 December 2009

Test report # : 560101-CC-1-a

3 Radiated emissions (full configuration)

