


Prüfbericht - Nr.:
Test Report No.:

16030075 002

Seite 31 von 33
Page 31 of 33

6 Photographs of the Test Set-Up

Photograph 1: Set-up for Conducted Emission Measurement




Photograph 2: Set-up for Radiation Measurement below 1GHz



Prüfbericht - Nr.:
Test Report No.:

16030075 002

Seite 32 von 33
Page 32 of 33



Photograph 3: Set-up for Radiation Measurement above 1GHz

