
Test Setup Photos


NINA-B400 of antenna 3 RADIATED EMISSION TEST SETUP BELOW 1GHZ



RADIATED EMISSION TEST SETUP ABOVE 1GHZ




NINA-B401 of antenna 3 RADIATED EMISSION TEST SETUP BELOW 1GHZ



RADIATED EMISSION TEST SETUP ABOVE 1GHZ



NINA-B411 of antenna 3 RADIATED EMISSION TEST SETUP BELOW 1GHZ



RADIATED EMISSION TEST SETUP ABOVE 1GHZ



Note: All test modes had been tested. The antenna 3 is the worst case and recorded in the report.

CONDUCTED EMISSION TEST SETUP

