




TEST PHOTOGRAPHS

1.1.Photos of power line conducted emission measurement

EUT



Front view of conducted measurement



Side view of Conducted measurement

opyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

Complaint line: +86-20-85533471








1.2.Photos of Radiated Emission Test (In Anechoic Chamber)

30~230MHz (X position)

EUT



230~1000MHz (X position)

EUT



EUT

above 1000MHz (X position)



opyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

CENTRE OF TESTING SERVICE CO., LTD.

 Building F, Dachuang industrial park, No.379, Zhongshan Dadao, Guangzhou, China

 Tel: +86-20-85543113 (32 lines)
 Fax: +86-20-38780406

 Complaint line: +86-20-85533471
 E-mail: cts@cts-lab.com.cn

See Reverse For Terms And Conditions of Service

Report No.: CGZ3100507-01559-O Page 2 of 3

FCC ID: XQGQRF900-TR1







1.3. Band Edge Compliance Test

X position

EUT



opyright of this report is owned by Centre of Testing Service and may not be reproduced other than in full except with the written approval of the issuing Company.

Building F, Dachuang industrial park, No.379, Zhongshan Dadao, Guangzhou, China Tel: +86-20-85543113 (32 lines) Fax: +86-20-38780406

Complaint line: +86-20-85533471 E-mail: cts@cts-lab.com.cn

See Reverse For Terms And Conditions of Service

Report No.: CGZ3100507-01559-O Page 3 of 3