





10 20 30 40 50 60 70





PCB broken during disassembly for photographs






C2

300-0065

U1

U2





10 20 30 40

mm

30

20

10