


## 7 Photographs of the Tests

### 7.1 Power line Conducted Emission Test (at Mains Terminals)




Front View




Rear View

## 7.2 Radiated Disturbances Emission Test



Below 1 GHz (EUT at 0.8m)



Above 1 GHz (EUT at 1.5m)