


| Test report No. | FCC_RF_SL16031001-SPC-003_0412 |
|-----------------|--------------------------------|
| Page | 12 of 69 |

6.6 EUT Test Setup Photos



Note: The spurious emission in different EUT orientation was investigated, including the EUT standing up position and the laying down position. The EUT orientation shown in above setup photo is the worst case position.