


Test report No.	FCC_RF_SL16072901-SPC-007_0205
Page	11 of 69

6.6 EUT Test Setup Photos

Internal Antenna:




Note: The spurious emission in different EUT orientation was investigated, including the EUT standing up position and the laying down position. The EUT orientation shown in above setup photo is the worst case position.



Test report No.	FCC_RF_SL16072901-SPC-007_0205
Page	12 of 69

External Antenna:



Note: The spurious emission in different EUT orientation was investigated, including the EUT standing up position and the laying down position. The EUT orientation shown in above setup photo is the worst case position.