


Test report No.	FCC_RF_SL16103101-SPC-006-LAA
Page	10 of 75

## 6.5 EUT Test Setup Photos

## **Internal Antenna:**




Note: The spurious emission in different EUT orientation was investigated, including the EUT standing up position and the laying down position. The EUT orientation shown in above setup photo is the worst case position.



Test report No.	FCC_RF_SL16103101-SPC-006-LAA
Page	11 of 75

## **External Antenna:**



Note: The spurious emission in different EUT orientation was investigated, including the EUT standing up position and the laying down position. The EUT orientation shown in above setup photo is the worst case position.