





## Internal Photographs

<Photograph 1: Cover removed>






<Photograph 2: Main board - Front view>






<Photograph 3: Main board (RF module shielding removed)>






**<Photograph 4: Main board - Rear view>**






<Photograph 5: P14421-F board - Front view>






<Photograph 6: P14421-F board - Rear view>





<Photograph 7: P15854 board - Front view>



오류!

<Photograph 8: P15854 board - Front view>





<Photograph 9: Nickel-metal hydride battery>

