

Photo Report on Test Setups Car-Access-Module

This Photo Report contains the photos of the radiated tests in the 7layers test reports:
MDE_HUF_1709_FCCa
MDE_HUF_1709_FCCb
MDE_HUF_1709_FCCc

Test Report Reference: MDE_HUF_1709_FCC_Photo_Report

Test Laboratory:

7layers GmbH
Borsigstrasse 11
40880 Ratingen
Germany



Note:

The following test results relate only to the devices specified in this document. This report shall not be reproduced in parts without the written approval of the test laboratory.

7layers GmbH
Borsigstraße 11
40880 Ratingen, Germany
T +49 (0) 2102 749 0
F +49 (0) 2102 749 350

Geschäftsführer/
Managing Directors:
Frank Spiller
Bernhard Retka
Alexandre Norré-Oudard

Registergericht/registered:
Düsseldorf HRB 75554
USt-Id.-Nr./VAT-No. DE203159652
Steuer-Nr./TAX-No. 147/5869/0385

a Bureau Veritas
Group Company

www.7layers.com

Photo 1: Test setup for radiated emissions measurements in semi-anechoic chamber (9 kHz to 30 MHz), front side view



Photo 2: Test setup for radiated emissions measurements in semi-anechoic chamber (30 MHz to 1 GHz), front side view




Photo 3: Test setup for radiated emissions measurements in fully-anechoic chamber (1 GHz to 26 GHz), front side view

